The Village Hall Schedule of Condition

Appendix A



Left elevation




Left elevation



Left elevation



Vegetation growth to left elevation




Previous creeper to left elevation




Left elevation




Rear elevation




Dip in ridge




Rear elevation



Rear elevation window




Rear elevation window



Extension from the rear



Drainage inspection chamber




Right elevation




Rear elevation



Vegetation growth to rear elevation




Window to rear elevation




Dip in ridge



Roof from the rear



Left elevation



Left elevation



Rear elevation



Extension to right elevation



Front elevation



Entrance to front elevation



Entrance to front elevation



Access ramp to front elevation



Secondary entrance & ramp to front elevation



Waste pipe to front elevation



Roof void




Roof void




Roof void




Roof void




Roof void




Entrance hall




Entrance hall



Entrance hall




Kitchen




Gas boiler



Cooking facilities




Kitchen




Door to kitchen








Main hall




Lighting to hall




Main hall walls




Main hall



Walls to main hall




Condensation to walls




Condensation to walls



False ceiling




Condensation to main hall walls




Condensation to main hall walls



Toilets



Toilets



Toilets



Entrance to ladies / dis WC



Dis WC



Damaged brickwork to access ramp



Damaged brickwork to access ramp



Current parking provisions



Boundary fencing